

CABLE ASSEMBLY INSTRUCTION

Maple Model(s)
HMI5000 Series (COM1)

PLC or Controller
Aerotech Soloist, Ensemble
Controllers


Communication Type
RS-232 with DE9
Connector at Controller



Summary

Use the wiring diagram and illustration to assemble a communication cable for use with an Aerotech Soloist HLe/HPe, or Ensemble EPaq/HLe/HPe/EPaqMR controller.

Drawing and Schematic



MAPLE HMI END

**CONTROLLER
END**

NOTES:

- 1 Shield wire must be terminated to connector metal shell.

