




Controller Model: **Configuration Cable**
 Maple OIT Model: **Silver (HMI500) Series**
 Communication Type: **RS-232 with DE9 Connector at PC**

Use the wiring diagram and illustration to assemble a configuration cable for communication between the HMI and your PC.

HMI 500 SERIES CONFIGURATION CABLE



NOTES:

- 1 Solder shield wire to the DE9S connector metal shell. Install heatshrink tubing over the shield wire to avoid shorting.

