

TECHNICAL NOTE

Maple Model(s)

Title

TN5098

Graphic HMI

Screenshots with EZware

P/N: 0907-5098

Rev. 01 Date: 06/15/2015



Summary

EZware provides the option of taking a screenshot of the windows in the project for documentation or other purposes.

Solution

To take a screenshot of a window in a project:

1. Open the project in EZware and run the Online Simulator or Offline Simulator (Tools > Online Simulation or Offline Simulation).
2. In the simulator, navigate to the window you want to use for the screenshot.
3. Right-click on the simulator and select "Screenshot."



4. A bitmap file of the window is saved to the Screenshot folder in the EZware folder (C:\MapleSystems\EZ5000\Screenshot or C:\MapleSystems\EZPlus\Screenshot). The bitmap file has the same name as the project with a number added to the end of the filename (for example, HMI5070THDemo_0000.bmp, HMI5070THDemo_0001.bmp, etc.).
5. The bitmap file can be imported directly into a Word document or opened in a graphics program such as Paint for enhancement or modification.